

AccuRad™

Check Source Jig



- Fixture for performing pre-operational checks and routine preventive maintenance
- Provides consistent detector-to-source geometry to ensure accurate measurements
- Uses exempt quantity Cs-137 button source (5-8 μ Ci activity). Reference rates provide for easy accuracy checks
- Source is secured by spring clip to prevent inadvertent displacement



Part # 7095627

